


HYUNDAI R430LC-9SH EXCAVATOR

SWING BEARING DIAGRAM



PART NUMBER & ALTERNATIVES:

81NA-01020; 81NA-10021; 81NA-01021BG;
81NA-01022BG; 81QA-01051

HYUNDAI



888-983-7847

WWW.CONEQUIP.COM

© 2018 CONEQUIP PARTS & EQUIPMENT LLC