


HYUNDAI R480LC-9A EXCAVATOR

SWING BEARING DIAGRAM



PART NUMBER & ALTERNATIVES:
81QB-01020; 81QB-01021; 81KB-01020

HYUNDAI



888-983-7847
WWW.CONEQUIP.COM