


HYUNDAI R500LC-7A EXCAVATOR

SWING BEARING DIAGRAM



PART NUMBER & ALTERNATIVES:

81NB-01021; 81NB-01022; 81NB-01021BG;
81NB-01022BG

HYUNDAI



888-983-7847

WWW.CONEQUIP.COM

© 2018 CONEQUIP PARTS & EQUIPMENT LLC