


HYUNDAI R140LC-9 EXCAVATOR

SWING BEARING DIAGRAM



PART NUMBER & ALTERNATIVES:

81N4-01020; 81N4-01021; 81N4-01021GG;
81N4-01022GG

HYUNDAI



888-983-7847

WWW.CONEQUIP.COM

© 2018 CONEQUIP PARTS & EQUIPMENT LLC