


HYUNDAI R220LC-9 EXCAVATOR

SWING BEARING DIAGRAM



PART NUMBER & ALTERNATIVES:
81Q6-00020; 81Q6-00021; 81Q6-01080

HYUNDAI



888-983-7847

WWW.CONEQUIP.COM

© 2018 CONEQUIP PARTS & EQUIPMENT LLC