


HYUNDAI R225LC-7 EXCAVATOR

SWING BEARING DIAGRAM



PART NUMBER & ALTERNATIVES:

81N6-00021; 81N6-00022; 81N6-00022BG;
81N6-00023BG

HYUNDAI



888-983-7847

WWW.CONEQUIP.COM

© 2018 CONEQUIP PARTS & EQUIPMENT LLC