


HYUNDAI R250LC-7 EXCAVATOR

SWING BEARING DIAGRAM



PART NUMBER & ALTERNATIVES:

81EN-00051; 81EN-00052; 81EN-00052BG;
81EN-00053BG

HYUNDAI



888-983-7847

WWW.CONEQUIP.COM

© 2018 CONEQUIP PARTS & EQUIPMENT LLC