


HYUNDAI R290LC-9 EXCAVATOR

SWING BEARING DIAGRAM



PART NUMBER & ALTERNATIVES:

81N8-00021; 81N8-00022; 81N8-00023BG;
81N8-00023GG; 81Q8-01051

HYUNDAI



888-983-7847

WWW.CONEQUIP.COM

© 2018 CONEQUIP PARTS & EQUIPMENT LLC